



# BROADCAST WORKS!

*Technical Excellence*

Ph: 888.509.2470  
Fax: 903.509.0880

2105 Anthony Drive  
Tyler TX 75701

10 May 2010

Exhibit 8, Explanation for Construction

To whom it may concern,


As a result of a voluntary self-inspection, it was found there was a coordinate discrepancy between the KMHT-FM license and its registered tower, ASRN 1237449.

To obtain an accurate measurement a surveyor was retained to measure the location of the tower. It was determined that neither the tower registration nor the license listed the correct NAD 27 coordinates of 32-33-49 N, 094-21-07.

An FAA Determination of No Hazard was obtained in Study Number 2010-ASW-1627-OE and a new form 854 was filed on line with the Commission, application A0683701.

The purpose of this application is to correct the coordinates on the face of the license.

Sincerely,



Harry Hardisty  
Staff Engineer