

> From: "Mike" <

[1. mjohanson@kathrein.com](mailto:1.mjohanson@kathrein.com)>

> To: "Chris Compton (E-mail)" <[xmtr.doc@verizon.net](mailto:xmtr.doc@verizon.net)>

> Sent: Friday, October 15, 2004 10:00 AM

> Subject: Correct KSD pdf copy of Pattern

>

>

>> Mr. Compton ,

>>

>> I have attached the 2xCA5-FM/CP/RM/CV KMRO-FM2 Pattern with the main lobe

> at 0degrees to match the Comstudy file we supplied to you on 6/17/04. I

>> apologize for working the 134 degree rotation into the pdf copy of the

> data you submitted for the KMRO-FM2 application. I believe the error in the

>> rotation was a miss-construe on my part as to what you were requesting.

>> Please accept the attached pattern with the corrected rotation of

> 0degrees.

>> If your self or the Commission need any further detail on where the

> mistake was made, please do not hesitate to contact me directly.

>>

>> Best regards,

>>

>> Mike Johnson

>> Broadcast Sales Engineer

>> Kathrein Inc., Scala Division

>> Ph: (541) 779-6500 ext 5126

>> fax: (541) 779-6575

>> [mjohanson@kathrein.com](mailto:mjohanson@kathrein.com)

>> <http://www.kathrein-scala.com/>