

Minor Modification to
Licensed Translator W201BS
Utica, New York

Page 1 of 2

Purpose

It was recently brought to our attention that the original tower registration for W201BS was filed in error. On August 7, 1997, an engineer no longer employed by our organization registered a tower to complete the original application for a new FM translator. The owner of the tower we are actually located on has properly registered his tower at the correct coordinates. A letter with similar language will be sent to your Gettysburg, PA office explaining the situation so we can have the incorrect registration deleted from the FCC database.

The purpose of this application is to correct the tower coordinate and antenna registration number errors for the licensed translator W201BS. Page #2 of this exhibit is a map showing that the 1mV/m (60dBu) of the modified translator overlaps most of the 1mV/m (60dBu) of the original W201BS, therefore, qualifying this as a minor modification according to 47 C.F.R. §74.1233.

Changes to section III-A – Engineering

Question 4 – Antenna Location and Coordinates.

The antenna location will be moved from 43-08-43 N, 075-10-34 W (ASR #1027184) to 43-08-34 N, 075-10-33 W (ASR #1044680).

Exhibit 12

This exhibit will show that W201BS will not cause any interference to any adjacent stations.

Exhibit 13

This is a study generated by PROBE II showing that the modified translator W201BS does not cause interference to WRGB TV 6.

W201BS 60 dBu Overlap

