

BENJAMIN F. DAWSON III, PE
THOMAS M. ECKELS, PE
STEPHEN S. LOCKWOOD, PE
DAVID J. PINION, PE

PAUL W. LEONARD, PE
ERIK C. SWANSON, PE
THOMAS S. GORTON, PE
MICHAEL H. MEHIGAN, EIT

HATFIELD & DAWSON
CONSULTING ELECTRICAL ENGINEERS
9500 GREENWOOD AVE. N.
SEATTLE, WASHINGTON 98103

TELEPHONE (206) 783-9151
FACSIMILE (206) 789-9834
E-MAIL hatdaw@hatdaw.com

JAMES B. HATFIELD, PE
CONSULTANT

MAURY L. HATFIELD, PE
CONSULTANT
OAKHURST, NSW
AUSTRALIA

MULTIPLE OWNERSHIP SERVICE CONTOUR ANALYSIS

**Prepared for
South Sound Broadcasting, LLC
June 2009**

The attached analysis of compliance with the radio multiple ownership rules was prepared in accordance with the Rules and Regulations of the Federal Communications Commission, in connection with an application for minor modification of FM station KOMO-FM on Channel 249C at Oakville, Washington.

The only other attributable station in the vicinity is KLSY Channel 300A South Bend.

Unrated Market Analysis

An ownership analysis has been made consistent with the Commission's interim rules for unrated markets. The 70 dBu contours of FM stations were determined from the technical data contained in the most recent edition of the FCC FM Database. The listed antenna height above average terrain was used together with topographic data obtained from the digitized 30 second or 3 second database. The 5 mV/m daytime contours of AM stations were determined from the technical data contained in the most recent edition of the FCC AM Database. The listed antenna parameter information was used together with a digitized version of the FCC M-3 or Region II ground conductivity database.

The service contours were plotted using correct map projection mathematics. Those stations whose transmitter sites are within the respective principal community service contours of the stations proposed to be commonly owned have only the sites rather than their contours shown. All contours and enclosed transmitter site locations have been labeled. A list of all stations considered is included with this statement.

Hatfield & Dawson Consulting Engineers

In counting stations providing service to the “market” defined by each of the discrete clusters formed in unrated markets, stations whose transmitter sites are located in excess of 92 km from the perimeter of the common overlap area have been excluded, as have other stations to be commonly-owned but which do not have overlap with the discrete cluster being studied.


This exhibit evidences at least the minimum number of stations necessary to demonstrate compliance with the rules concerning radio multiple ownership in unrated markets. In order to qualify for common ownership of this 2FM cluster, there must be at least four stations in the relevant “market”. This study demonstrates that there are at least 20 stations in the relevant market.

June 10, 2009



Erik C. Swanson, P.E.

Transmitter Site Key	
A	KMAS(AM) Shelton
B	KGY(AM) Olympia
C	KXRO(AM) Aberdeen
D	KUOW(AM) Tumwater
E	KBKW(AM) Aberdeen
F	KWOK(AM) Hoquiam
G	KLOP(FM) Ocean Park
H	KAOS(FM) Olympia
I	KPLI(FM) Olympia
K	KANY(FM) Ocean Shores
J	KRXY(FM) Shelton
K	KXXX(FM) Hoquiam
L	KGY-FM McCleary
N	KOMO-FM Oakville (App)
N	KDDS-FM Elma
O	KSWW(FM) Elma
P	KNBQ(FM) Centralia
K	KDUX-FM Aberdeen
G	KJET(FM) Raymond
G	KLSY(FM) South Bend



KOMO-FM Ownership Study
 0 10 20 30
 Kilometers
 Hatfield & Dawson 6/2009