

**R. M. SMITH ASSOCIATES**  
BROADCAST TECHNICAL CONSULTANTS  
4267 NW FEDERAL HIGHWAY #120 - JENSEN BEACH, FL 34957  
(772) 335-0688 FAX (772) 335-1438  
E-MAIL [bob@rmsmith.com](mailto:bob@rmsmith.com)


**ENGINEERING STATEMENT**

**ON BEHALF OF WILKS LICENSE COMPANY-RENO LLC  
KURK(FM) – RENO, NV**

**REQUEST FOR SPECIAL TEMPORARY AUTHORIZATION**

The KURK(FM) transmitter has suffered a series of failures in its power amplifier and is currently operating at reduced power. Repeated consultations with the transmitter manufacturer have, as yet, not resolved the problem. The factory has suggested a test procedure, but severe winter weather and heavy snow coverage have prevented access to the site with the test equipment required. The licensee will complete tests and repairs as soon as the site conditions permit.

The licensee hereby requests temporary authority to operate the facility at less than the licensed TPO pending repairs to the transmitter equipment. It is expected that KURK(FM) will be operating at full power within sixty days.



---

Robert M. Smith Jr.

Technical Consultant