

4/18/2018

To Whom it May Concern:


Upon testing the resistance on the WLDX antenna I have determined that the resistance has changed less than 1% from the previous license value.

I was also asked to check the tower painting, light beacon, bulb, and coax. This tower is in remarkable shape with only very little paint flaking. The beacon looks good and the bulb is in working order. Upon checking the coax, I find no problems to note.

The door to the gate is secure and the fencing has no noticeable issues. Effort has been made to trim the grass in and outside the fenced in area.

Please contact me for any further engineering needs. It was great to see you and best wishes with the FM translator.

Sincerely,

A handwritten signature in black ink, appearing to read "Ross Swanner", with a long, sweeping horizontal stroke extending to the left.

Ross Swanner

IBS Engineering