

## EXHIBIT 29

In recent years RF measurements have been made on the Lookout Mountain electronic site. As a result of some of the measurements KALC has been operating at reduced power under a Special Temporary Authority. The overall situation is under study and steps will be taken to bring KALC into compliance with their licensed authority. The results of those studies and descriptions of any corrective actions will of course be submitted to the Commission. Obviously, since no physical changes are being made, the minor changes in the license parameters of record, as proposed in this application, have no bearing on the calculated or measured RF levels at the transmitter site.

Prepared by

**LOHNES AND CULVER**

8309 Cherry Lane

Laurel, MD.

April, 2002