

BERNARD R. SEGAL, P. E.  
CONSULTING ENGINEER  
KENSINGTON, MARYLAND

---

EXHIBIT 22  
ENGINEERING STATEMENT  
STA OPERATION  
STATION W06AJ, FRANKLIN, ETC. NC

Station W06AJ has suffered wind damage to two of the four vertically stacked Taco, Yagi, Model Y-103-6 antennas that comprise its antenna system. Pursuant to Section 73.1680(b)(2) of the FCC Rules, the remaining two undamaged antenna units are being used for emergency operation while arrangements for a replacement antenna are being made.

The emergency antenna results in a 3 dB drop in effective radiated power from 0.467 kW to 0.234 kW. The horizontal plane radiation pattern remains unchanged from that for the licensed operation. The emergency antenna operation does not extend coverage in any direction.

The instant STA request is for a period of 180 days.