

EXHIBIT NO. 1

ENGINEERING STATEMENT
APPLICATION FOR MODIFICATION OF
CONSTRUCTION PERMIT
WEIGEL BROADCASTING COMPANY
STATION WRDY-LP
SOUTH BEND, INDIANA
CH 25 37.8 KW (MAX-DA) 587 M AMSL

This exhibit has been prepared on behalf of Weigel Broadcasting Company, licensee of LPTV station WRDY-LP South Bend, Indiana, Facility ID 24617. While constructing the facility authorized in File Number BMPTTL-20020311AAJ, it was discovered that the geographic coordinates describing the tower location were incorrect, thereby placing the tower 1.8 kilometers due south of the actual location. The Federal Aviation Administration was immediately notified of the correct geographic coordinates, and after receiving a "Determination of No Hazard", the tower registration was modified to reflect the actual tower coordinates. The purpose of this exhibit is to modify the construction permit by substituting the correct geographic coordinates for the constructed tower.

The correct geographic coordinates for the tower as determined by survey are:

41° 36' 55" North Latitude

86° 11' 07" West Longitude.

South Bend, Indiana
Page 2 of 2

The ground elevation and tower height as shown in the permit is correct and unchanged. In addition, there is no change in the proposed antenna radiation center height.

Even though the apparent change in tower location is only 1.8 kilometers, study was undertaken to determine that the proposed operation would comply with pertinent allocation criteria. All pertinent domestic LPTV, Class A, NTSC and DTV stations and proposals were carefully reviewed for potential objectionable interference. No objectionable interference was determined, employing normal study methods and use of the Longley-Rice propagation model. In addition, the predicted 19 dBu [F(50,10)] field strength contour will not reach the closest point on the U.S./Canadian border.

Except for the change in geographic coordinates, all technical information contained in File Number BMPTTL-20020311AAJ remains unchanged.



Louis R. du Treil, Sr.
du Treil, Lundin & Rackley, Inc.
201 Fletcher Avenue
Sarasota, Florida 34237-6019
941 329 6000

October 7, 2002