



Antennas • Filters

Kathrein Inc., Scala Division

P.O. Box 4580

Medford, OR 97501 USA

Phone: 541-779-6500

Fax: 541-779-6575

mail@kathrein.com

www.kathrein-scala.com

November 17, 2006

Ms. Lois Mills
Calvary Chapel of Twin Falls, Inc.
P. O. Box 391
Twin Falls, ID 83303

**Ref: BMPFT-20061023AAV
W201CP Binghamton, NY**

Dear Ms. Mills,

Thank you for your letter and documentation concerning the proposed co-location of translator W201CP on the same tower with existing translator W283AG.

We feel that the vertical spacing (24 meters) between your proposed and existing installations is more than sufficient to prevent any significant effect to the directional characteristics of the existing antenna radiation pattern.

We also feel that the location of your antenna feeder cable will have no effect to the directional characteristics of the existing installation.

This opinion carries no performance guarantee and is based solely on the data provided by Calvary Chapel of Twin Falls and the practical experience of our sales engineers. It is by no means a comprehensive analysis and Kathrein-Scala recommends Calvary Chapel to engage the services of a qualified communications consulting firm for a definitive evaluation. The furnished data has not been verified by Kathrein-Scala for completeness or accuracy.

If we may be of further assistance, please do not hesitate to contact us.

Best regards,

Michael Wm. Bach, Sales Engineer
Kathrein Inc., Scala Division
Email: mbach@kathrein.com
Ph: (541) 779 6500 Ext. 128; Fx: (541) 779 6575
Direct: (541) 618 5128
MWB/jy