

EXHIBIT 11

Calvary Chapel of Twin Falls, Inc.
March 2003

Sequim, WA
K219KP / BLFT-20021226AAC
Facility ID #93040

Calvary Chapel of Twin Falls, Inc. is making this minor change to the above referenced Licensed Station, to modify its TX Antenna System and increase ERP. The transmit antenna is located on a mast on top of a building and that will not change. Please see TOWAIR results that show this structure does not need to be registered with the FCC because it is less than 20 feet tall on an existing building.

CCTF would also like to bring to the Commissions Attention that the pattern found in the CDBS Public Access, Search For Antenna Information, Scala CA2, FM, Standard Pattern #16124 and non standard pattern #58194 is that of Scala CA5 patterns and not CA2 patterns. The Standard FM CA2 pattern is located under non standard antenna pattern # 30696, which is also the antenna pattern being used in this application.

EX 11 – Explanation and Exhibits being Submitted

EX 12 – Compliance and Waiver Request

EX 12 – Canadian Terrain Compliance