

JAMES B. HATFIELD, PE
BENJAMIN F. DAWSON III, PE
THOMAS M. ECKELS, PE
STEPHEN S. LOCKWOOD, PE
DAVID J. PINION, PE

PAUL W. LEONARD, PE
ERIK C. SWANSON, EIT
THOMAS S. GORTON, PE

HATFIELD & DAWSON
CONSULTING ELECTRICAL ENGINEERS
9500 GREENWOOD AVE. N.
SEATTLE, WASHINGTON 98103

TELEPHONE
(206) 783-9151
FACSIMILE
(206) 789-9834
E-MAIL
hatdaw@hatdaw.com

MAURY L. HATFIELD, PE
CONSULTANT
BOX 1326
ALICE SPRINGS, NT 5950
AUSTRALIA

MULTIPLE OWNERSHIP SERVICE CONTOUR ANALYSIS

**Prepared for
Combined Communications, Inc.
October 2004**

The attached analysis of compliance with the radio multiple ownership rules was prepared in accordance with the Rules and Regulations of the Federal Communications Commission.

Unrated Market

All of Combined Communications' stations are located within the Bend, Oregon, market:

KBND(AM)	1110 kHz	Bend
KTWS(FM)	252C3	Bend
KMTK(FM)	259C3/C2	Bend
KLRR(FM)	269C2	Redmond

The Bend market is not rated by Arbitron. Therefore, analysis has been made consistent with the Commission's interim rules for unrated markets. The 70 dBu contours of FM stations were determined from the technical data contained in the most recent edition of the FCC FM Database. The listed antenna height above average terrain was used together with topographic data obtained from the digitized 30 second or 3 second database. The 5 mV/m daytime contours of AM stations were determined from the technical data contained in the most recent edition of the FCC AM Database. The listed antenna parameter information was used together with a digitized version of the FCC M-3 or Region II ground conductivity database.


The service contours were plotted using correct map projection mathematics. Those stations whose transmitter sites are within the respective principal community service contours of the

stations proposed to be commonly owned have only the sites rather than their contours shown. All contours and enclosed transmitter site locations have been labeled. A list of all stations considered is included with this statement.

In counting stations providing service to the "market" defined by each of the discrete clusters formed in unrated markets, stations whose transmitter sites are located in excess of 92 km from the perimeter of the common overlap area have been excluded, as have other stations to be commonly-owned but which do not have overlap with the discrete cluster being studied. This exhibit evidences at least the minimum number of stations necessary to demonstrate compliance with the rules concerning radio multiple ownership in unrated markets.

It should be noted that the instant analysis applies equally to the licensed facilities of the Combined Communications stations, as well as to the pending application facilities for the three FM stations.

October 22, 2004

A handwritten signature in black ink, appearing to read "Erik C. Swanson". The signature is fluid and cursive, with the first name "Erik" and last name "Swanson" clearly distinguishable.

Erik C. Swanson

AM STATIONS WITH 5 mV/m CONTOURS OVERLAPPING
70 dBu CONTOURS OF KTWS, KMTK, KLRR
AND 5 mV/m CONTOUR OF KBND

Call Status	City St Co	FCC File No.	Freq Mode	Power(kW) Hrs Cls	Latitude Longitude
=====					
KRCO	PRINEVILLE		690	1.000	N 44-20-28
LIC	OR US	BL0000404ACK	ND2	DAY B	W 120-54-24
KICE	BEND		940	10.000	N 44-04-47
LIC	OR US	BL0020920ADV	DA2	DAY B	W 121-16-59
KBND	BEND		1110	10.000	N 44-06-25
LIC	OR US	BL19970428AC	DAN	DAY B	W 121-14-39

FM STATIONS WITH 70 dBu CONTOURS OVERLAPPING
70 dBu CONTOURS OF KTWS, KMTK, KLRR
AND 5 mV/m CONTOUR OF KBND

Call Status	City State	FCC File No.	Channel Freq.	ERP(kW) HAAT(m)	Latitude Longitude
=====					
KWRX LIC	REDMOND OR	BLED020612AAU	203C3 88.5	0.250 DA 670.0	44-26-14 120-57-12
KVLB LIC	BEND OR	BLED030730BCL	213A 90.5	0.500 172.0	44-04-40 121-19-48
KOAB-FM LIC	BEND OR	BLED860128KC	217C2 91.3	25.000 184.0	44-04-41 121-19-57
KXIX LIC	BEND OR	BLH860710KA	231C 94.1	100.000 303.0	44-02-48 121-31-53
KLTW-FM LIC	PRINEVILLE OR	BLH850916KA	236C1 95.1	100.000 144.0	44-18-32 120-55-47
KWLZ-FM LIC	WARM SPRINGS OR	BLH860127KG	243C 96.5	100.000 332.0	44-50-24 121-13-56
KNLR LIC	BEND OR	BLH850114LW	248C1 97.5	97.000 163.0	44-04-38 121-19-49
KTWS LIC	BEND OR	BLH950629KC	252C3 98.3	6.800 191.0	44-04-41 121-19-57
KTWS APP	BEND OR	BPH040405ABG	252C3 98.3	5.200 223.0	44-04-39 121-19-57
KMTK LIC	BEND OR	BLH000620ADR	259C3 99.7	7.000 DA 189.0	44-04-40 121-19-49
KMTK APP	BEND OR	BMPH040405ABH	259C2 99.7	26.000 DA 208.0	44-04-39 121-19-57
KMGX LIC	BEND OR	BLH5892	264C1 100.7	50.000 158.0	44-04-40 121-19-49
KLRR LIC	REDMOND OR	BMLH990419KF	269C2 101.7	27.500 202.0	44-04-41 121-19-57
KLRR APP	REDMOND OR	BPH040405ABF	269C2 101.7	23.000 223.0	44-04-39 121-19-57
KSJJ LIC	REDMOND OR	BLH941108KA	275C1 102.9	100.000 270.0	44-02-48 121-31-53
KWPK-FM LIC	SISTERS OR	BLH010516AAI	281C2 104.1	34.000 180.0	44-04-40 121-19-49
KQAK LIC	BEND OR	BMLH010522AAO	289C1 105.7	40.000 180.0	44-04-40 121-19-49

