## PLEASE STAMP AND RETURN THIS COPY TO THIS COPY TO THIS COPY TO THIS COPY TO THIS COPY TO

ROBERT J. BUTLER HARRY F. COLE ANNE GOODWIN CRUMP DONALD J. EVANS PAUL J. FELDMAN KEVIN M. GOLDBERG DAVID M. JANET FRANK R. JAZZO M. SCOTT JOHNSON DANIEL A. KIRKPATRICK TONYS. LEE CHENG-YI LIU STEPHEN T. LOVELADY ASHLEY LUDLOW JONATHAN R. MARKMAN SUSAN A. MARSHALL HARRY C. MARTIN MICHELLE A. McCLURE MATTHEW H. McCORMICK FRANCISCO R MONTERO RAYMOND J. QUIANZON DAVINA SASHKIN PETER TANNENWALD JAMES U. TROUP KATHLEEN VICTORY

1300 NORTH 17th STREET, 11th FLOOR ARLINGTON, VIRGINIA 22209

> OFFICE: (703) 812-0400 FAX: (703) 812-0486 www.fhhlaw.com www.commlawblog.com

December 14, 2015

Accepted / Filed

DEC 1 4 2015

Federal Communications Commission Office of the Secretary RETIRED MEMBERS
VINCENT J. CURTIS, JR.
RICHARD HILDRETH
GEORGE PETRUTSAS
JAMES P. RILEY

OF COUNSEL
THOMAS J. DOUGHERTY, JR.
ROBERT M. GURSS\*
KATHRYN A. KLEIMAN
MITCHELL LAZARUS
ROBERT J. SCHILL
LAURA A. STEFANI
ROBERT M. WINTERINGHAM

\* NOT ADMITTED IN VIRGINIA

PETER TANNENWALD (703) 812-0404 TANNENWALD@FHHLAW.COM

Marlene H. Dortch, Secretary Federal Communications Commission Washington, DC 20554

Re:

W32BJ, Facility ID 69449, Beaufort, SC File No. BLSTA-20141217AAD

FRN 0003-7596-51

Attention:

Video Division, Media Bureau

Dear Ms. Dortch:

The above-referenced file number refers to a request by Southern TV Corporation for authority for Station W32BJ to remain silent, beginning December 12, 2014. The CDBS and LMS databases were not changed to show the station as silent, so the licensee is unable to open and file a notice of resumption of operation in LMS and must provide notice by a paper filing.

I have been informed by the President of the licensee that W32BJ resumed operation at 6:30 p.m. on December 12, 2015. Attached is a photograph sent to me of a receiver displaying the signal, along with a newspaper dated December 12.

I have also been advised that operation resumed with the licensed facilities authorized under File No. BLTT-19970401JB. However, the final tube failed when the transmitter was activated, with the result that, although the licensed antenna is being used, the transmitter output

## Fletcher, Heald & Hildreth

Marlene H. Dortch, Secretary

Re: W32BJ, Facility ID 69449, Beaufort, SC

Page 2

is only approximately 4 watts. The transmitter is old enough that finding a replacement tube will be difficult. If full power operation cannot be restored within 10 days, a notice of operation at reduced power will be required.

If there are any questions about this matter, please contact the undersigned.

1 me

Counsel for Southern TV Corporation

Attachment

cc: (w/att) Mr. Dan L. Johnson

Mr. Hossein Hashemzadeh

## Savannah 2

\$2.00

SATURDAY, DECEMBER 12, 2015 SAVA



## Training accid

over Fort Stewart corporal, 21, dies after live f

nsider