

COHEN, DIPPELL AND EVERIST, P. C.  
CONSULTING ENGINEERS  
RADIO-TELEVISION

DONALD G. EVERIST, PE  
PRESIDENT

THOMAS G. LOCKE

CONSULTANT

ROBERT P. ECKERT, PE

1420 N STREET, N.W.  
SUITE ONE  
WASHINGTON, D. C. 20005  
(202) 898-0111

JULIUS COHEN  
(1913-1993)

RALPH E. DIPPELL, JR.  
(1922-1992)

FACSIMILE  
(202) 898-0895

E-MAIL:  
CDEPC@COMCAST.NET

July 12, 2016

Ms. Marlene Dortch  
Secretary  
Federal Communications Commission  
445 12<sup>th</sup> Street, SW  
Room TW-B204  
Washington, DC 20554

Re: WFND-LD, Findlay, Ohio  
Facility ID: 21475  
Resumption of Operation

Dear Ms. Dortch:

This letter is to update the Federal Communications Commission regarding efforts to restore WFND-LD transmission to the air. As previously reported on June 27, 2016, WFND-LD notified the Commission that on June 3, 2016 due to a transmitter malfunction, WFND-LD was off the air.

WFND-LD also reported that its technical staff had tried to engage the remaining transmitter manufacturer representatives in order to gain guidance to restore the transmitter operation. However, those efforts were unfruitful. The WFND-LD technical staff was able to finally restore operation at approximately 70% power on July 1, 2016. This is after several failed attempts to restore operation. The Commission will be updated appropriately as the WFND-LD technical staff continues to restore WFND-LD to full licensed power.

If there should be any questions, please do not hesitate to contact me.

Sincerely,

  
Donald G. Everist

Consulting Engineer for WFND-LD

DGE:cc

cc: Fred Vobbe

Jason Rademacher