

STA Request
NPG of Monterey-Salinas CA, LLC
KMUV-LP, Monterey, California

General Information Exhibit: Justification for STA

This exhibit is to advise the Commission that KMUV-LP is operating at 69% power as a result of a failure within the station's power amplifier. At the time of the instant request, the damaged part has been sent to the manufacturer for repair or replacement. Because the repaired or replacement part has not yet been delivered, the licensee respectfully requests special temporary authority for a period of 60 to 90 days to continue to operate at reduced power until a repaired or replacement amplifier is delivered to the station and installed in the transmitter.

* * * * *