

#### EXPLANATION OF STATION STATUS

Licensee is waiting for other stations at site to complete repack antenna installations so a final RF Exposure study can be completed. An interim study was completed and current RF exposure levels are within FCC limits.