

Antenna Technical Data Correction

**Univision New York LLC**

WFUT-DT Newark, NJ facility ID 60555

Auxiliary Antenna

Channel 26 240 kW-DA 224 m

An error was made when entering the antenna data on the corresponding CP application, LMS file [0000217852](#).

Antenna Technical Data was erroneously pre-filled in the CP application by selection of an antenna ID for the same antenna, but that data represented a different frequency and does not exactly match WFUT's parameters. The correct antenna pattern was filed with the application. The correct pattern data was also used in the contour comparison and interference analysis filed in the application.

The Antenna Technical Data fields have been corrected on the instant License to Cover application. The maximum difference of the changes is 0.086 dB.