

**KCGE-DT License to Cover Application for Coordinate Corrections
Explanation of Modifications and Permit Condition**

This construction permit was for correction of transmitter coordinates of -4.2 seconds in latitude and -3.3 seconds in longitude; because the coordinate correction was greater than ± 3 seconds in latitude or longitude, an application for a construction permit was required rather than a simple license application. There is no change in the physical location of the tower, the effective radiated power, or the transmitting antenna pattern or height. Notification to any health care facilities within the KCGE-DT coverage area was given prior to the station's commencement of operation from the Euclid site on or about October 23, 2004. Because there is no change in frequency, location, ERP or transmitting antenna pattern or height, it is believed that a repeated notification is not required.