

Exhibit 1 to Pre-Auction Technical Certification for WDVB-CD Facility ID 168834

There is a discrepancy in the Database Technical Information for this station's antenna. The correct manufacturer is PSI, and the correct model is PSIUP-23.

The station's license to cover application form FCC 302-CA (BLDTA - 20120227ABY), section III, part 6, states antenna type PSIUP-23.

The station's authorization, and the LMS Facility Technical Data both show the antenna as DIE TUAC2F – this is the antenna from the original CP, and was substituted during construction. The antenna pattern is identical, so there is no impact to the contour or other technical parameters of the station.