

FCC Form 2100

For

WKIN-CD

Exhibit 1.b.

Due to an undetected clerical error on WKIN-CD's "flash cut" application for a construction permit (CP) to switch from analog to digital operation, the same 0.26 kilowatt power was shown for both effective radiated power (ERP) and transmitter power output (TPO). The construction permit (CP), which was granted, and the station license covering that CP also reflect 0.26 kilowatts as both the TPO and the ERP.

The correct ERP is 0.26 kilowatts as shown all three of the above-referenced documents; however, the correct TPO is 0.1 kilowatts, which is the TPO, which the station ran before the "flash cut" occurred and has continued to run since.