

FCC Schedule 381 for KNDU, Richland, WA  
7/13/15  
KHQ, Incorporated  
PO BOX 600.  
Spokane, WA 99210

A newer antenna structure analysis has not been done for this tower. The wind and structural loading has not been changed.

Paul I. Caryl

Director of Engineering  
KHQ, Incorporated