

## **Construction Mistake Discovered and Regularized**

KYOM-LP recently learned that our antenna had been built at the wrong height. This occurred under previous management and appears to have been a construction miscommunication because the built antenna height matches the authorized HAAT, and there appears to be enough excess feedline to mount the antenna to the approved height AGL.

As soon as the discrepancy was discovered, Sunflower discontinued operation and filed a request for silent authority (BLSTA-20200916AAG). Investigation revealed that the previously-authorized ERP is also allowable at the built height and does not violate RF Safety nor second-adjacent interference requirements. We requested authorization to operate at the built height which was granted, and we are now operating by authority of the recently-granted license (0000131173).

Our organization has always endeavored to be compliant as the record will show. We regret this mishap and respectfully request the Commission's forbearance.