

**W286DV
SPECIAL OPERATING CONDITIONS**

Special Operating Conditions or Restrictions:

The permittee/licensee in coordination with other users of the site must reduce power or cease operation as necessary to protect persons having access to the site, tower or antenna from radiofrequency electromagnetic fields in excess of FCC guidelines.

Acknowledged and will comply.

THE W286DV (FAC ID 140342), FACILITY SPECIFIED IN FILE# 157391, CAN NOT COMMENCE OPERATION UNTIL W284DS, SPECIFIED IN FILE# 157389, CHANGES ITS FREQUENCY TO CHANNL 284. LICENSE APPLCIATIONS COVERING FILE # 157389 AND FILE # 157391 MUST BE FILED SIMULTANEOUSLY.

The two facilities have been constructed and their licenses to cover are hereby filed simultaneously.

Prior to commencing program test operations, FM Translator or FM Booster permittee must have on file an application for an FM Translator or FM Booster Station License, pursuant to 47 C.F.R. Section 74.14.

Filed herewith.



Charles M. Anderson
cmanderson43@yahoo.com