

### Basis for STA Request

Due to a malfunctioning main transmitter, Station KMKS has been forced to operate at reduced power utilizing the station's backup transmitter. Specifically, it has been operating at approximately 10% of authorized power since May 23, 2022. Licensee has ordered replacement parts and made arrangements for installation. In the interim, STA to continue operating at 10% power is respectfully requested. Licensee will promptly notify the Commission when the station is able to resume full-power operations.