

WYCOLP resumed normal operations after the completion of moving the station transmission antenna and transmitter to new location. Station also requested a change from a 1 bay antenna back to the original 2 bay antenna system.