


The application is amended to correct a typographic error concerning the proposed directional antenna relative field value at 230 degrees (non-rotated radial bearing). The correct value is 0.086 for radial value.

No other changes are required. This error occurred on the form only.

February 27, 2023

A handwritten signature in blue ink, appearing to read "Timothy Z Sawyer". The signature is fluid and cursive, with a large initial "T" and "S".

Timothy Z Sawyer, Technical Consultant
(703) 848-2130