

**Notification of Reduced Power Operations**

On July 18, 2023, the transmitter for WVRI(FM) (Facility ID No. 177072) unexpectedly failed. Liberty University, Inc. ("Liberty"), promptly replaced the failed transmitter with a smaller spare and is currently operating WVRI(FM) at approximately 50% of the facility's authorized power. Given the foregoing, Liberty respectfully submits this notification of reduced power operations.

The failed transmitter is currently being assessed for potential repair; Liberty is also sourcing a potential replacement transmitter in the event repair is not possible. If the timeline for repair or replacement exceeds 30 days, Liberty will timely submit an engineering STA request for continued reduced power operations.

\* \* \* \* \*