

Justification for Extension of Silent STA

The licensee has corrected the issue with the transmitter for W248CM. However, the translator now cannot receive a clean off-air signal from the primary station, WOXL-FM. Moving the receive antenna to a different location on the tower will hopefully restore reception. Meanwhile, the translator must remain silent.