

Doug Holland, Inc.  
331 Main Street  
Trussville, AL 35173  
205.229.5628

Spurious Measurement Report for W MMJ Transmitter facility, 4001 Nebraska Ave, Washington, D.C.

On December 21, 2009 I, Doug Holland, personally measured WKYS-FM & WMMJ-FM for compliance with FCC Rules 73.317(b) through 73.317(d) as a requirement of the FM Broadcast Station Construction Permit Auxiliary Antenna Permit File Number **BXPH-20090306ABB**

Observations made on the Agilent YE4407B Spectrum Analyzer Serial Number MY47111170 showed no products of either carrier above -80 dBc up to 1.5 GHz. A tunable notch filter inserted in the spectrum analyzer input allowed the individual carrier to be attenuated by 60 db to allow for improved analyzer sensitivity on the unnotched channel. The notch filter was tuned to each channel in turn and measurements made. No change in the spectrum was noted.

Certified  Date 1/10/09

Doug Holland

P1-7-13278