

**EXHIBIT**

CXR Holdings, Inc. ("CXR") recently learned that, prior to its acquisition of WBLI(FM), a license application for WBLI(FM) was submitted with a discrepancy that has been reflected in the station's license. Specifically, the station's antenna is a Shively 6810-5D-SS-DA. As described in the attached Technical Exhibit prepared by du Treil, Lundin & Rackley, Inc., the original proof-of-performance, the licensed surveyor's affidavit, and the engineering supervisor's affidavit and certification that were submitted with the station's license application (and previously filed STA requests) identified the correct antenna model number. The license application form, however, identified an incorrect antenna model number of Shiveley 6810-4R-DA, apparently as a result of an inadvertent clerical error. Upon discovering this discrepancy, CXR has acted promptly to investigate the issue and take steps to remedy the error. By this application, CXR seeks only to correct the station's license to reflect the proper antenna model number.