

FEDERAL COMMUNICATIONS COMMISSION
445 TWELFTH STREET SW
WASHINGTON DC 20554

MEDIA BUREAU
AUDIO DIVISION
APPLICATION STATUS: (202) 418-2730
HOME PAGE: www.fcc.gov/media/radio/audio-division

ENGINEER: Joseph Szczesny
TELEPHONE: (202) 418-2700
FACSIMILE: (202) 418-1410
E-MAIL: Joseph.Szczesny@fcc.gov

December 18, 2017

Lenard D. Liberman, President
Liberman Broadcasting of Dallas License LLC
1845 Empire Avenue
Burbank, CA 91504

Re: Liberman Broadcasting of Dallas License LLC
(LBDL)
KZMP(AM), University Park, TX
Facility Identification Number: 63551
Special Temporary Authority (STA)
BESTA- 20171127AAO

Dear Mr. Liberman:

This is in reference to the request filed on November 27, 2017. LBDL requests an extension of the STA granted on June 5, 2017, to continue to operate with reduced nighttime power using a temporary transmitter to allow time to file the required FCC Form 302 application (due to lightning damage).¹ In support of the request, LBDL states that additional time is needed to complete all repairs.

Requests for extension of STA will be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.

¹ KZMP(AM) is licensed for DA operation on 1540 kHz with 32 kW day and 0.75 kW night using different patterns.

Accordingly, the request for extension of the STA IS HEREBY GRANTED, and LBDL may continue to operate with nighttime DA parameters at variance and reduced power (with no change to the daytime licensed operation). LBDL must use whatever means are necessary to protect workers and the public from exposure to radio frequency radiation in excess of the Commission's exposure guidelines. See 47 CFR § 1.1310. LBDL must file the required FCC Form 302 application if any significant changes to the operating parameters are needed after the transmitter and phasor have been repaired (or replaced with new equipment). Otherwise LBDL must submit an e-mail to my attention to certify the date the station resumed licensed operations (per BL-20020809ABT) with negligible changes to all operating parameters.

This authority expires on **June 18, 2018**.

Sincerely,

A handwritten signature in blue ink, consisting of a series of loops and a long horizontal stroke extending to the right.

Joseph Szczesny, Engineer
Audio Division
Media Bureau

cc: Kathleen A. Kirby, Esq., WR LLP (via email only)