

3/31/04

Engineering Statement of Tom King

Re: KCRU Directional Antenna installation

1. Antenna was side-mounted on a Triex 303 tower section in accordance with Antenna Manufacturers instructions.
2. Antenna is not mounted on top of an antenna tower which has a top-mounted platform larger than the nominal cross-sectional area of the tower in the horizontal plane.
3. Antenna is mounted at a level where there are other antennas, however, the antenna is designed to minimize coupling to those antennas and will have no effect on pattern. There are no other antennas that are mounted within any horizontal or vertical distance specified by the antenna manufacturer as being necessary for proper directional operations.
4. I have over 15 years of Broadcast Engineering experience and have installed over 50 directional FM broadcast antennas. I certify that the antenna was installed pursuant to the manufacturer's instructions.

Signed,

A handwritten signature in black ink, appearing to read "Tom King", written in a cursive style.

Tom King CSRE