

EXHIBIT 1 (continued)

Part C

Overlap of Service Areas

Figure 1 of Part C of this Exhibit shows the 60 dBu contours for the pending proposed FM translator on Channel 232D and for the amended FM translator on Channel 232D, to establish that there would be overlap of the service areas of the respective translator facilities.

The predicted contours shown in Figure 1 of Part C were determined in accordance with the requirements of Section 73.313 of the Commission's Rules, from computerized calculations based on the NGDC 30-second terrain database and Figures 1 and 1a of Section 73.333 of the Rules. Distances to the contours were calculated at azimuthal increments of one degree.

Fred W. Volken  
Engineering Consultant

April 2013

Sierra Madre, California

EXHIBIT 1, PART C (continued)

FIGURE 1

Overlap of Service Areas

