

FCC Form 854

Sandlin Broadcasting Co., Inc. received Notice of Dismissal of it's FCC for 854 dated 02/02, 2003, Reference No 271230, and File No A0311179.

**Sandlin Broadcasting Co., Inc filed utilizing the old NAD83 standard instead of the adjusted NAD27. The correct NAD27 Latitude is W28-47-50.0, Longitude N96-09-21.0 for the existing KMKS antenna structure.
FAA 98-ASW-3054-OE.**