



**FEDERAL COMMUNICATIONS COMMISSION**  
**WASHINGTON, D. C. 20554**

January 14, 2010

Thompson Falls TV District  
P.O. Box 519  
Thompson Falls, MT 59873

1800E1-TN

In re: Low Power Television Application of:  
Thompson Falls TV District  
Channel 50, Thompson Falls, MT  
File number: BNPDTT-20090825AIL  
Facility Id No.: 181907

Dear Applicant:

We are currently processing your above-referenced application. A search of the FCC tower registration database, found at <http://wtbwww05.fcc.gov/antenna/ASRQuery.html>, reveals that discrepancies exist between the data listed for the antenna tower structure referenced in your application and the FCC's tower registration database. (Please note that all coordinates found in the FCC tower registration database are NAD 83 and that the conversion from NAD 27 may be required before requesting a search.)

You are required to electronically amend your application to resolve these specified problems within (30) days of the date of this letter. If not so amended electronically, your application will be **CONSIDERED INCOMPLETE AND SUBSEQUENTLY DISMISSED**.

Sincerely

Hossein Hashemzadeh  
Associate Chief  
Video Division  
Media Bureau