

**FEDERAL COMMUNICATIONS COMMISSION**  
**445 TWELFTH STREET SW**  
**WASHINGTON DC 20554**

MEDIA BUREAU  
AUDIO DIVISION  
APPLICATION STATUS: (202) 418-2730  
HOME PAGE: [www.fcc.gov/mb/audio/](http://www.fcc.gov/mb/audio/)

ENGINEER: CHARLES N. (NORM) MILLER  
TELEPHONE: (202) 418-2767  
FACSIMILE: (202) 418-1410  
E-MAIL: [charles.miller@fcc.gov](mailto:charles.miller@fcc.gov)

April 22, 2010

Brendan Holland, Esq.  
Davis Wright Tremaine LLP  
1919 Pennsylvania Avenue NW, Suite 200  
Washington, DC 20006-3402

Re: Rincon Broadcasting LS LLC  
KSBL(FM), Carpinteria, California  
Facility Identification Number: 35592  
Special Temporary Authority

Dear Counsel:

This is in reference to the request filed February 2, 2010, on behalf of Rincon Broadcasting LS LLC ("RB"). RB requests further extension of the special temporary authority ("STA") granted on December 2, 2008, to operate Station KSBL with temporary facilities.<sup>1</sup> In support of the request, RB states that repairs to the licensed site, which had been extensively damaged by fire, were nearly complete when the site was again damaged to an even greater extent by a second fire. RB states that it holds a construction permit to relocate the transmitter and that it is evaluating whether or not to restore the currently licensed facilities due to the susceptibility of the site to wildfires.

Requests for extension of STA will be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.

Our review indicates that the licensee has been prevented from restoring licensed operation due to causes beyond its control and has taken all possible steps to expeditiously resolve the problem. Thus, extension of STA is warranted.

Accordingly, the request for extension of STA IS HEREBY GRANTED. Station KSBL may

---

<sup>1</sup> KSBL is licensed for operation on Channel 269A (101.7 MHz) with effective radiated power of 0.994 kilowatt (H&V) and antenna height above average terrain of 245 meters.

continue to operate with the following facilities:

Geographic coordinates:	34° 28' 15" N, 119° 40' 33" W (NAD 1927)
Channel	269 (101.7 MHz)
Effective radiated power:	0.51 kilowatt (H&V)
Antenna height:	
above ground:	7 meters
above mean sea level:	730 meters
Above average terrain:	335 meters

RB must notify the Commission when licensed operation is restored. RB must use whatever means are necessary to protect workers and the public from exposure to radio frequency radiation in excess of the Commission's exposure guidelines. *See* 47 CFR § 1.1310.

This authority expires on **October 22, 2010**.

Sincerely,

A handwritten signature in blue ink, appearing to read "Charles N. Miller", with a long horizontal flourish extending to the right.

Charles N. Miller, Engineer  
Audio Division  
Media Bureau

cc: Rincon Broadcasting LS LLC