

FEDERAL COMMUNICATIONS COMMISSION
445 TWELFTH STREET, SW
WASHINGTON, DC 20554

MEDIA BUREAU
AUDIO DIVISION
APPLICATION STATUS: (202) 418-2730
HOME PAGE: www.fcc.gov/mb/audio/

ENGINEER: Frank Takacs
TELEPHONE: (202) 418-2700
FACSIMILE: (202) 418-1410/1411
MAIL STOP: 1800B3
INTERNET ADDRESS: Frank.Takacs@fcc.gov

MAR 23 2015

Columbia Chinese Christian Church
3316 Rock Quarry Road
Columbia, MO 65201

Re: KLJE-LP, Columbia, MO
Facility ID No. 132417
Columbia Chinese Christian Church
File No. BPL-20150313AAA


Dear Applicant:

The staff has under consideration the above-captioned minor modification application.

An engineering study has revealed that the proposed transmitter site specified in the application fails to meet the minimum spacing requirements of 47 C.F.R. § 73.807. Specifically, the site proposed is located 37.1 kilometers from licensed commercial station KTXY(FM) on channel 295C in Jefferson, MO (BLH-19900727KA). The required spacing pursuant to § 73.807 is 93 kilometers. The application fails to address this defect.

Accordingly, in light of the above, application BPL-20150313AAA is unacceptable for filing and IS **HEREBY DISMISSED**. This action is taken pursuant to 47 C.F.R. § 0.283 and 73.870(c).

Sincerely,


For James D. Bradshaw
Deputy Chief
Audio Division
Media Bureau