

I, John Anderson, Contract Engineer of Wallingford Communications, I.L.C. do hereby certify the following.

That I have been a holder of an F.C.C. Radio-Telephone License since 1986 and have been actively engaged in broadcast engineering since that time. Also have been responsible for the construction of several transmitter facilities.

I referenced a set of mounting instructions provided by Jampro, the antenna manufacturer and supervised the installation for WFLX-FM, Berea, F.C.C. File Number BPH-19990512IL. A detailed inspection determined that the antenna was installed exactly according to the manufacturer's instructions. In addition, I inspected the installations to verify the following:

- 1.) That no platforms on the structure are larger than the nominal cross sectional area of the tower in the antenna horizontal plane.
- 2.) No additional antennae are located within the area of the antenna, vertical or horizontal.
- 3.) The tower and all cables, steps etc., are properly grounded.

Upon a complete and thorough examination, I can conclude that the directional antenna has been installed exactly as specified by the mounting instructions from Jampro.



John Anderson.

(1/26/01)