

**KATHREIN**  
SCALA DIVISION

February 3, 2004

**Antennas • Filters****Kathrein Inc., Scala Division**

P.O. Box 4580

Medford, OR 97501 USA

Phone: 541-779-6500

Fax: 541-779-3991

mail@kathrein.com

www.kathrein.com

Attn: Ms. Lois Mills  
Calvary Chapel of Twin Falls Inc.  
4002 N 3300 E  
Twin Falls ID 83301  
Fax: (208) 736-1958**Ref: BPFT-2004012ABP K259AK**

Dear Ms. Mills,

Thank you for your narrative and site drawing. Having reviewed the information you provided, we believe that the installation of your K259AK transmitting antenna and coaxial cable will have no significant effect on the directional pattern of the existing K207CP FM translator station.

This opinion carries no performance guarantee and is based solely on the data provided by Calvary Chapel of Twin Falls, Inc. and the practical experience of our sales engineers. It is by no means a comprehensive analysis and Kathrein-Scala recommends Calvary Chapel of Twin Falls, Inc. to engage the services of a qualified communications consulting firm for a definitive evaluation. The furnished data has not been verified by Kathrein-Scala for completeness or accuracy.

Please feel free to contact me if you need further assistance.

Best regards,

Michael Wm. Bach, Sales Engineer  
Kathrein Inc., Scala Division  
Email: mbach@kathrein.com  
Ph: (541) 779 6500 Ext. 128; Fx: (541) 779 6575  
Direct: (541) 618 5128  
MWB/jy