

Received & Inspected

CALVARY CHAPEL OF TWIN FALLS, Inc.

PO Box 391
4002 N. 3300 E.
Twin Falls, ID 83303
Ph(208)734-6633 Ext. 206 – Fax (208)736-1958
loism@csnradio.com

JUN 10 2015

FCC Mail Room

June 3, 2015

Office of the Secretary
Attn: Chief, Audio Division, Media Bureau
Federal Communications Commission
445 12th Street, SW
Washington, DC 20554

ATTENTION: FM Branch, Mass Media Bureau
REFERENCE: KGSF Huntsville, Arkansas
Facility ID No: 92987 / 10 day Notification

Dear Staff:

Calvary Chapel of Twin Falls, Inc.(CCTF) respectfully notifies the Commission that KGSF Huntsville, Facility ID 92987, is operating at a reduced power since May 26, 2015, when the transmitter began having problems. The 2.5kW transmitter has been shipped back to the factory for repairs and has been replaced with a temporary 250 watt transmitter. It is expected to take 2-3 weeks before the transmitter will be repaired and shipped back. If normal operations have not resumed within the specified 30 days an STA request, to operate at reduced power, will be electronically filed.

Sincerely,



Lois Mills
Applications Technician
Calvary Chapel of Twin Falls, Inc.