

FM Commander Contour-to-Contour - HAAT Method= 4 @V-Soft Communications®

File Print Settings Class Channel < Down > Up Find Views Help About

IX Issue! AM tower NGDC 30 SEC DATA: 04-07-11 East Zone

N. Lat. 32 38 09.0 160.9 M COR Contours are detailed Marion AL X wjus fx.vsf
 W. Lng. 87 18 08.1 0.25 kW CH 232, 94.3 D 81.6 M HAAT * Job: 04-07-11

Call	Type	Ch	Location		Azi	Dist	In	Out
W232AN	LIC	232D	Suttle	AL	134.8	16.4	19.2*	25.0
WZBQ	LIC	231C0	Carrollton	AL	311.4	98.5	-16.6*	12.5
WJOX-FM	LIC-N	233C0	Birmingham	AL	24.5	101.0	-16.0*	10.6
WQZX	LIC	232A	Greenville	AL	140.7	103.8	6.0	30.3
WDJC-FM	LIC	229C0	Birmingham	AL	23.5	97.8	74.7	23.3
WHOD	LIC-N	233C2	Jackson	AL	199.9	135.9	46.1	64.1

End of Screen List

In: is kilometers of overlap "received" by translator app
 (the translator app is allowed to receive interference)

Out: is kilometers of overlap "**caused**" by translator app
 (the translator app is not allowed to cause interference to co-channel or 1st adjacent stations)

The proposed operation of this FM translator fully complies with the rules regarding Fill-In Operations for an AM Station

ASR: 1278005 has already received approval from the FAA. No physical change in AM location proposed.

FM Translator Contour Overlap Analysis - Ch. 232 from WJUS AM Site - As Corrected



Grace Baptist Temple Church
 W232AN - Marion, AL
 April 2011