

March 25, 2013

To whom it may concern

I reviewed our file (Shop Order 26404) for WGVZ and found that the 6810-2R-SS-DA is mounted on the Union Metal pole on top of the IDS building pointing at an azimuth bearing of 315° True.

If the coax transmission line feeding the KNOF antenna is attached to the pole exactly where a recently removed transmission line was located, there will be no measurable effect on the directional pattern of the WGVZ antenna.

If you have any questions or need more information, please do not hesitate to contact me.

Robert A Surette



Director of Sales Engineering

CC: Shop orders 26404 & 30613