

AUDIO SERVICES DIVISION

CALVARY CHAPEL OF TWIN FALLS, Inc.

PO Box 391
4002 N. 3300 E.
Twin Falls, ID 83303
Ph(208)734-6633 – Fax (208)736-1958

Received & Inspected

NOV 19 2012

FCC Mail Room

2012 NOV 20 A 6:01

November 13, 2012

Mr. Charles N (Norm) Miller
Federal Communications Commission
Audio Services Division
445 12th Street, SW
Washington, DC 20554


ATTENTION: FM Branch, Mass Media Bureau
REFERENCE: Resumption of Normal Operations/BSTA-20120820AAU
STATION: WUJC St. Marks, Florida, Facility ID 122209

Dear Mr. Miller:

Calvary Chapel of Twin Falls, Inc., Licensee of WUJC (FM) St. Marks, Florida, Facility ID 122209, hereby notifies the Commission that licensed operations were restored to when the transmitter was fully repaired on November 7, 2012.

Calvary Chapel of Twin Falls, Inc. respectfully requests that BSTA-20120820AAU, granted August 21, 2012, be dismissed. If you have any questions concerning this letter, please contact me at (208)733-3133 ext 206, or by email at loism@csnradio.com. Thank you.

Sincerely,



Lois Mills
Application Technician
Calvary Chapel of Twin Falls, Inc.

Received & Inspected

FEDERAL COMMUNICATIONS COMMISSION
445 TWELFTH STREET SW
WASHINGTON DC 20554

NOV 19 2012

FCC Mail Room

MEDIA BUREAU
AUDIO DIVISION
APPLICATION STATUS: (202) 418-2730
HOME PAGE: www.fcc.gov/mb/audio/

ENGINEER: CHARLES N. (NORM) MILLER
TELEPHONE: (202) 418-2767
FACSIMILE: (202) 418-1410
E-MAIL: charles.miller@fcc.gov

August 21, 2012

Lois Mills
Calvary Chapel of Twin Falls, Inc.
Box 391
Twin Falls, Idaho 83303

Re: Calvary Chapel of Twin Falls, Inc.
WUJC(FM), St. Marks, Florida
Facility Identification Number: 122209
Special Temporary Authority

Dear Ms. Mills:

This is in reference to the request filed August 20, 2012, on behalf of Calvary Chapel of Twin Falls, Inc. ("CCTF"). CCTF requests special temporary authority ("STA") to operate Station WUJC with reduced power.¹ In support of the request, CCTF states that the station's transmitter has been damaged by lightning. CCTF states that some of the damaged components have been replaced, but that it still is waiting for two additional circuit boards from the manufacturer.

Section 73.1560(d), which governs reduced power operation, states:

In the event it becomes technically impossible to operate at authorized power, a broadcast station may operate at reduced power for a period of not more than 30 days without specific authority from the FCC. If operation at reduced power will exceed 10 consecutive days, notification must be made to the FCC in Washington, DC, Attention: Audio Division (radio) or Video Division (television), Media Bureau, not later than the 10th day of the lower power operation. In the event that normal power is restored within the 30 day period, the licensee must notify the FCC of the date that normal operation was restored. If causes beyond the control of the licensee prevent restoration of the authorized power within 30 days, a request for Special Temporary Authority (see Section 73.1635) must be made to the FCC in Washington, DC for additional time as may be necessary.

Our review indicates that the request complies with Section 73.1560(d).

¹ WUJC is licensed for operation on Channel 216C3 (91.1 MHz) with effective radiated power ("ERP") of 7 kilowatts (V only) and antenna height above average terrain ("HAAT") of 95 meters. Construction Permit BNPED-20110224ABL authorizes relocation of the transmitter, an upgrade to Class C1, an increase in ERP to 73.5 kW (Max-DA, V only) and an increase in HAAT to 139 meters.

Accordingly, the request for STA IS HEREBY GRANTED. Station WUJC may operate with reduced power. CCTF must notify the Commission when licensed operation is restored. CCTF must use whatever means are necessary to protect workers and the public from exposure to radio frequency radiation in excess of the Commission's exposure guidelines. See 47 CFR § 1.1310.

This authority expires on **November 20, 2012**.

STA Advisory: Section 309(f) of the Communications Act of 1934, as amended, authorizes the Commission to grant STA in cases of "extraordinary circumstances requiring temporary authorizations in the public interest and when delay in the institution of the temporary operations would seriously prejudice the public interest." However, Section 309(f) is not a means by which a licensee/permittee may circumvent established processing procedures which require the filing of an application, nor is it a means by which a broadcaster may enhance his facility or make operation more convenient for the broadcaster. Stations operating with less than licensed facilities under temporary authorities can be viewed as receiving the benefit of a larger protection area than that in which they are currently providing service.

Accordingly, Special Temporary Authorities by nature are to be temporary and are not intended for extended use. Licensees of stations operating under temporary authorities are reminded that timely restoration of permanent facilities is the responsibility of the licensee and should be undertaken expeditiously. Any request for extension of special temporary authorities carries an increased burden with each subsequent request.

Therefore, requests for extension of STA will be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.

Sincerely,



Charles N. Miller, Engineer
Audio Division
Media Bureau

cc: Calvary Chapel of Twin Falls, Inc.