

Dilicast

Broadcast Services

P.O. Box 97483
Raleigh, NC 27624
(919) 341-4699 Office

“Diligence in Broadcasting”

May 29, 2012

WEFC-TV STA Application Exhibit 21

WEFC's main broadcast transmitter's tube has failed. The tube used is no longer available from the manufacturer. The current reduced TPO is being produced by the solid state driver amplifiers bypassing the failed tube. WEFC is currently operating at the reduced ERP of 6.304KW with a TPO of 200watts.

WEFC is currently seeking a replacement transmitter. It is estimated replacement will be possible within 6 months.

Sincerely,



Thomas I Hoots
Dilicast Broadcast Services
Raleigh, NC