

Condition #3 on the K284AE construction permit requires an exhibit including a statement from the manufacturer of the K257BO and K282AY directional antennas, stating that the K284AE antenna will have no adverse effect on the directional antenna patterns of the other two translators. This condition is predicated on an assumption that the K257BO and K282AY antennas are located on the same tower structure as the K284Ae antenna.

In fact, the K282AY antenna is located on an adjacent 30 meter tower, not on the 52 meter tower which supports the K284AE antenna. The 30 meter tower is located about 30 feet from the K284AE tower.

The K257BO antenna has been or is being removed, now that K257BO has been relocated to a different transmitter site. See pending license application BLFT-20140617AAS.

Therefore the K284AE antenna would not affect the K257BO and K282AY directional patterns, and no further exhibit is believed to be necessary.