

Exhibit 2
FCC Form 346
Section I
Item 5, Displacement
Garden valley translator District
P.O. Box 711
Garden Valley, ID 83622

Interference measurements K10OA-D and KNIN-D

July 1, 2012 Measurements were made of KNIN-D with K10OA-D turned off. Measurements were made using a Sencore SLM1475 SN 21086 R17 connected to a Channel Master CM-3016 VHF/UHF antenna at 20 feet. Measurements were made by Larry E. Smith

11:19 AM Coordinates: 44 02' 21.6"N / 115 48' 44.2"W
Signal Measured -5 dBmv with very watchable picture.

11:43 AM Coordinates: 44 02' 18.78"N / 115 48' 27.64"N
Signal Measured -9 dBmv with watchable picture.

12:20 PM Coordinates: 44 01' 16.06"N / 115 50' 00.46"N
Signal Measured -28 dBmv with break up in picture.

With K10OA-D back on the air, KNIN-D was not viewable at any of these sites.