


Figure 2



SECTION 73.622(f)(5) COMPLIANCE

DTV STATION KRQE-DT
ALBUQUERQUE, NEW MEXICO
CH 13 21.5 KW 1287 M

du Treil, Lundin & Rackley, Inc. Sarasota, Florida