

## EXHIBIT 1

### ANTENNA SUPPORT STRUCTURE – STRUCTURAL ANALYSIS

The antenna support structure was built in 2001, per the applicable engineering codes for Puerto Rico. The tower has been periodically maintained, as required, but no structural analysis has been done after construction.