

It is believed that due to the age of this antenna structure, and the fact that it is a commercially designed, professionally installed, and well-guyed tower, it most likely met the structural standard of EIA RS-222A or B. It is in very good structural condition.