

**GREG BEST
CONSULTING, INC.**

13008 W. 67th St.
Shawnee, KS 66216
816-792-2913

July 8, 2015


Federal Communications Commission
Media Bureau—Video Division

Dear Sir,

This attachment is being submitted in order to assist the FCC is determining the last structural analysis that was executed for class A DTV station KLEG-CD.

As the licensee's RF technical consultant, I was involved with the transmission system planning at the time that the structural analysis was executed but do not have any information on who performed it and to what standard it was compared. The antenna is mounted on top of the Bank of America Plaza Bldg in Dallas, TX. There may have been different structural requirements imposed on the antenna support structure by the building owners in addition or beyond the scope of the TIA-222 relevant standard. Usually, the building has a civil engineer that reviews and organizes structural reviews. My only suggestion is to contact the Bank of America Plaza in Dallas, TX and its respective engineer to determine if any progress can be made ascertaining the structural engineer involved and to what standard the facility was compared

Sincerely,

A handwritten signature in black ink that reads "Greg Best, P.E." with a stylized flourish at the end.

President